

YELLOW JACKET® Replacement Sensor and Cable Upgrade

Mid 2011 - present



69086 with 69101 sensor and cable assembly



69101 cable and sensor assembly

Prior to mid 2011



69086 with 69087 replacement sensor and 40819 or 69088 replacement cable



69087

Sensor and cable now a factory assembled part to resolve the two pieces not connecting well in some cases

All 69086 Handheld Vacuum Gauges built since the middle of 2011 have included a detachable cord.

- The replacement part for this assembly is 69101
- This includes both the cable and the sensor

All 69086 hand-held vacuum gauges shipped prior to the middle of 2011 included a non-detachable cord and a separate sensor.

- The 69087 is the replacement sensor for these units
- The 69088 is the replacement cord for these units

The one piece cable/sensor assembly (69101) is now used on the Refrigeration System Analyzers 4081x as well. The RSA has always been built with a detachable cord and a detachable sensor. Replacement parts include the 40819 cord and the 69087 sensor. However, because the one-piece 69101 offers higher accuracy and more stable readings, we recommend that you always replace one or the other with the 69101.

UPC#	Description
69101	Replacement sensor and cord assembly
69087	Replacement sensor
40819	Replacement cable (newer detachable version)
69088	Replacement cable (older internal mount - not detachable)

