

YELLOW JACKET® Series 41 Manifold for R-22/134a/404A



42006 - with 60" PLUS II Hoses

Now available with 2-1/2" gauges

These new manifold part numbers are now available for customers currently buying 41212, 41213, and 41215 R12/22/502 manifolds who would like to update their refrigerants.

- 41202 - Manifold only
- 41209 - with 36" PLUS II Hoses, standard fittings
- 41211 - with 60" PLUS II Hoses, standard fittings

Replacement Gauges:

- 49015 - 2-1/2" Red Pressure
- 49016 - 2-1/2" Blue Compound

Preseason Pricing	1-49	50+
41202 No Hose/Clamshell	\$37.49	\$35.86
41211 60" RYB PLUS II Hose	\$60.49	\$57.87

Still available with 3-1/8" gauges

- 42005 - Manifold only
- 42006 - with 60" PLUS II Hoses, standard fittings

Replacement Gauges:

- 49105 - 3-1/8" Red Pressure
- 49106 - 3-1/8" Blue Compound

Preseason Pricing	1-49	50+
42005 No Hose/Clamshell	\$43.29	\$41.93
42006 60" RYB PLUS II Hose – Standard Fittings	\$72.76	\$70.48

