





# YJACK PATH™ Firmware Updater for MacOS

## INSTRUCTIONS:

1. Click the link below or type this URL into your web browser:  
<http://www.yellowjacket.com/downloads/mac/yjflash/yjflash.zip>
2. Download the YJFlash.zip file.
3. Using the Finder on your MacOS computer, go to the Downloads folder and double-click on the YJFlash.zip file. This will extract the YJFlash app and place it in the Downloads folder.




4. Double-click the YJFlash icon to run the app. If you choose, you can drag the icon onto your desktop or other location for easier future access.
5. You may receive a warning about opening an app developed by an unidentified developer like the




screenshots below.


6. If you receive one of these messages, navigate to System Preferences> Security and Privacy>General. Click "Open Anyway" to allow the YJFlash app to run. Return to the YJFlash app and double-click the icon to open the app.



7. Click on Path Radio Firmware tab (far right tab) on top program tabs.
8. Follow the on-screen instructions to perform the Radio Firmware updates.



For P51 instructions use left two tabs (see also P51-870 TITAN® update instructions)



NOTE: On newer versions of MacOS, you may need to allow "Input Monitoring" in System Preferences> Security and Privacy> Privacy. This is due to the USB communications used during the firmware update.